



Reade Advanced Materials

Temperature Conversion Chart

Converting Fahrenheit to Celsius	Converting Celsius to Fahrenheit
$((^{\circ}\text{F} - 32) \times (5/9)) = ^{\circ}\text{C}$	$(^{\circ}\text{C} \times (9/5)) + 32 = ^{\circ}\text{F}$

Celsius °C	Fahrenheit °F
0	32
10	50
20	68
25	77
28	82.4
50	122
100	212
150	302
200	392
250	482
300	572
350	662
400	752
450	842
500	932
550	1022
600	1112

Celsius °C	Fahrenheit °F
650	1202
700	1292
750	1382
800	1472
850	1562
900	1652
950	1742
1000	1832
1050	1922
1100	2012
1150	2102
1200	2192
1250	2282
1300	2372
1350	2462
1400	2552
1450	2642

Celsius °C	Fahrenheit °F
1500	2732
1550	2822
1600	2912
1650	3002
1700	3092
1750	3182
1800	3272
1850	3362
1900	3452
1950	3542
2000	3632
2050	3722
2100	3812
2150	3902
2200	3992
2250	4082
2300	4172

Celsius °C	Fahrenheit °F
2350	4262
2400	4352
2450	4442
2500	4532
2550	4622
2600	4712
2650	4802
2700	4892
2750	4982
2800	5072
2850	5162
2900	5252
2950	5342
3000	5432